

# **Technical data sheet** Host receiver termination

Part no.: 426127

AC-MLC-HR-END



## Contents

- Technical data
- Electrical connection
- Notes

# **Technical data**



#### Basic data

| Application  | Alignment and setup aid for MLC 520 Host versions |
|--------------|---|
| Suitable for | MLC 520 host receiver safety light curtains       |

### Connection

| Type of connection | Connector |
|--------------------|-----------|
| Thread size        | M12       |
| Туре               | Male      |
| No. of pins        | 8 -pin    |
| Encoding           | A-coded   |
| Version            | Axial     |

IP 67

#### Classification

| Customs tariff number | 85366990 |
|-----------------------|----------|
| ECLASS 5.1.4          | 27279201 |
| ECLASS 8.0            | 27440102 |
| ECLASS 9.0            | 27069190 |
| ECLASS 10.0           | 27440102 |
| ECLASS 11.0           | 27440102 |
| ECLASS 12.0           | 27440116 |
| ECLASS 13.0           | 27440116 |
| ECLASS 14.0           | 27440116 |
| ECLASS 15.0           | 27440116 |
| ETIM 5.0              | EC002635 |
| ETIM 6.0              | EC002635 |
| ETIM 7.0              | EC002635 |
| ETIM 8.0              | EC002635 |
| ETIM 9.0              | EC002635 |
| ETIM 10.0             | EC002635 |
|                       |          |

# **Electrical connection**

#### **Connection 1**

Degree of protection

| Type of connection | Connector |
|--------------------|-----------|
| Thread size        | M12       |
| Туре               | Male      |
| No. of pins        | 8 -pin    |
| Encoding           | A-coded   |
| Version            | Axial     |

# **Notes**

## WARNING!



Risk of injury due to insufficient safety distance

- b Integration of a Guest device results in an increase in reaction time. For this reason, a large safety distance must be allowed for.
- ♥ For further information, refer to calculation of the safety distance in the connecting and operating instructions.

# **WARNING!**



Risk of injury due to missing stepping behind protection

🖖 If the terminating plugs are used, take appropriate measures to ensure that it is not possible to step behind the safety light curtain.

# **WARNING!**



Risk of injury due to unforeseeable machine behavior

- \$ Changes made to the protective device can lead to unforeseeable machine behavior.
- $\ ^{\mbox{\tiny $t$}}\ \mbox{ After making changes, have the protective device checked by a qualified person.}$

# **Notes**



## NOTE

