

Technical data sheet Host transmitter termination

Part no.: 426126

AC-MLC-HT-END



Contents

- Technical data
- Electrical connection
- Notes

Technical data



Basic data

Application	Alignment and setup aid for MLC 520 Host versions
Suitable for	MLC 500 host transmitter safety light curtains

Connection

Connection 1	
Type of connection	Connector
Thread size	M12
Туре	Male
No. of pins	8 -pin
Encoding	A-coded
Version	Axial

IP 67

Certifications

Degree of protection

Classification

Customs tariff number	85366990
ECLASS 5.1.4	27279201
ECLASS 8.0	27440102
ECLASS 9.0	27069190
ECLASS 10.0	27440102
ECLASS 11.0	27440102
ECLASS 12.0	27440116
ECLASS 13.0	27440116
ECLASS 14.0	27440116
ETIM 5.0	EC002635
ETIM 6.0	EC002635
ETIM 7.0	EC002635
ETIM 8.0	EC002635
ETIM 9.0	EC002635

Electrical connection

Connection 1

Type of connection	Connector
Thread size	M12
Туре	Male
No. of pins	8 -pin
Encoding	A-coded
Version	Axial

Notes

WARNING!



Risk of injury due to insufficient safety distance

- b Integration of a Guest device results in an increase in reaction time. For this reason, a large safety distance must be allowed for.
- ♥ For further information, refer to calculation of the safety distance in the connecting and operating instructions.

WARNING!



Risk of injury due to missing stepping behind protection

🖖 If the terminating plugs are used, take appropriate measures to ensure that it is not possible to step behind the safety light curtain.

WARNING!



Risk of injury due to unforeseeable machine behavior

- \$ Changes made to the protective device can lead to unforeseeable machine behavior.
- $\ ^{\mbox{\tiny t}}\ \mbox{ After making changes, have the protective device checked by a qualified person.}$

Notes



NOTE



info@leuze.com • www.leuze.com